

**Carter Fabricating Inc.
326 Deerhurst Drive
Brampton, Ontario
L6T 5H9**

Attention: Mike Libreiro

Neutral Salt Spray Test: ASTM B117-11

Sample I.D.: EVOSTone Coating System

Exova Mississauga W/O # 522265
Ref. #G552286-Issue 1
May 8, 2015

EXOVA - CAMBRIDGE

Per:  **Marina Phady**
Corrosion Laboratory Technician

Per:  **Graham Rutherford**
Corrosion Department Manager

This report shall not be reproduced except in full, without the written approval of the laboratory. This presentation pertains only to the item(s) contracted to Exova by the client unless otherwise indicated.

This report and service are covered under Exova Canada Inc's. Standard Terms and Conditions of Contract which may be found on our company's website www.exova.com or by calling 1-886-263-9268.

Item 001: Salt Spray Test per ASTM B117-11.




Figure 1: Photograph illustrating the specimens prior to salt spray exposure.




Figure 2: Photograph illustrating the specimens after 500 hours of salt spray exposure. The specimens showed slight softening with no blistering, lifting, loss of adhesion or other visible changes. There was no loss of adhesion/creepback from the scribe.

Note: Creepback evaluation was conducted per ASTM D1654-08, Method 4 (Air Blow-Off).